

SPARCsystem 470 Hardware Installation Checklist

This *Checklist* guides you through the essential steps of the hardware installation for your server system and directs the system administrator to the starting point for the software installation. This *Checklist* refers to the right sequence of documents that contain more detailed information and procedures.

Installers Start Here:

- ☐ Verify that the site chosen for the SPARCsystem[™] 470 complies with the requirements for power and air conditioning for this system.
- ☐ As directed in the *12-Slot Office Pedestal Installation Manual*:
 1. Install the intercabinet cables found in the system accessories and hardware documents shipping container.
 2. Install the AC power-cord for the SPARCsystem 470 system pedestal.
 3. Power up the system.
- ☐ Give this *Checklist* to the System Administrator. *This is extremely important!*
- ☐ For more information, read the *SPARCsystem 470 System Hardware Overview* found in the system accessories and hardware documents shipping container.

System Administrators Start Here:

- ☐ Find and open the Release Distribution Media Box. There are several document boxes. Open the media box first. This box contains two tapes and several documents. (You can disregard the "Open First" label on the generic release box.)
- ☐ From the same Release Distribution Media Box, find and read the *SPARCsystem 470 Release Manual*, which will get you started with the installation process and its documentation.

